Rounding The process of cutting the digits of a measurement off at the uncertain digit, and/or when a measurement has run on numbers Rounding Rules 1. Always round to the uncertain digit, or 2 digits whatever is less 2. If the number after digit is 0 – 4 round down 3. If the number after digit is 5 – 9 round up

